


ThinWire



Skirting

Adjusting Light

Tighten grub screw on bracket with key to hold arm in desired position
Only move the arm with the screws loose to prevent a groove being made in the copper or the screws will not hold

